OBDLink U: Verifying Connection to Scan Tool

Start

↓

Disconnect all cables

↓

Plug in OBD-II cable

↓

"STATUS" LED on or flashing?

— No →

No Power on DLC

1. Remove/Reseat connector
2. Check fuses
3. Measure voltage between pins 5 and 16 (should be > 8 volts).

Yes ↓

Perform LED test

The **"LED Test"** is performed by simply disconnecting then re-connecting the OBDII cable from the vehicle while watching the lights on the scan tool. Do they appear to "sweep" across the face of the unit? This indicates a successful test.

↓

LED test OK? — No → **Bad scan tool, get RMA**

Yes ↓

Plug in USB cable

↓

Power LED color? — Red →

Troubleshoot USB Connection

1. Make sure the USB cable is securely plugged into the computer and scan tool.
2. Make sure the computer is powered on.

Amber or Yellow ↓

Run STN finder

↓

Found scan tool? — No → Close all applications that may be using the COM port

Yes ↓

Record COM port # and baud rate

↓

Close STN finder

↓

Optional:
Verify connection to ECU

↓

End